Location: BIG SKY TIRE & AUTO Sys Fac ID: 27-02343

495 US HIGHWAY 93 N Last Inspected On: 2/19/2015

EUREKA, MT 59917 LINCOLN Operating Permit Renewal Date: 3/21/2018

Contact: Ernie Roo, (406) 297-2623

Owners/Operators: EJ Properties LLC, Owner (406)-297-2623 PO BOX 629 EUREKA MT 59917

> Joey Burgess, UST Class A Operator Kary Tonjum, UST Class A Operator Joey Burgess, UST Class B Operator Kary Tonjum, UST Class B Global Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
1	22	10/1/1993	Cathodically Protected Steel	Fiberglass Reinforced Plastic	Positive Shutoff
1856			None	None	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Galvanic, Impressed Current
Diesel		2/16/2015	Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2	Automatic Tank Gauging 0.2, ELLD Line Tightness Testing	
12,000		11/14/2005	Gilbarco EMC Basic , Gilbarco		
6	35	5/6/1980	Cathodically Protected Steel	Fiberglass Reinforced Plastic	Ball Float Valve
1851			Lined Interior/Impressed Current	None	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Impressed Current
Gasoline		2/16/2015	Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2	Automatic Tank Gauging 0.2, ELLD Line Tightness Testing	
12,000		11/14/2005	Gilbarco EMC Basic , Gilbarco		
7	35	5/6/1980	Cathodically Protected Steel	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff)
1852			Lined Interior/Impressed Current	None	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Impressed Current
Gasoline		2/16/2015	Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2	Automatic Tank Gauging 0.2, ELLD Line Tightness Testing	
12,000		11/14/2005	Gilbarco EMC Basic , Gilbarco		

BIG SKY TIRE & AUTO Location:

Sys Fac ID: 27-02343 495 US HIGHWAY 93 N

Last Inspected On: 2/19/2015

EUREKA, MT 59917 LINCOLN **Operating Permit Renewal Date:** 3/21/2018

Ernie Roo, (406) 297-2623 Contact:

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
8	35	5/6/1980	Cathodically Protected Steel	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff)
1853			Lined Interior/Impressed Current	None	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Impressed Current
Gasoline		2/16/2015	Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2	Automatic Tank Gauging 0.2, ELLD Line Tightness Testing	
12,000		11/14/2005	Gilbarco EMC Basic , Gilbarco		
9	33	5/6/1982	Cathodically Protected Steel	Fiberglass Reinforced Plastic	Ball Float Valve
1854			Lined Interior/Impressed Current	None	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Impressed Current
Diesel		2/16/2015	Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2	Automatic Tank Gauging 0.2, ELLD Line Tightness Testing	
6,000		11/14/2005	Gilbarco EMC Basic , Gilbarco		
10	26	5/6/1989	Cathodically Protected Steel	Fiberglass Reinforced Plastic	Positive Shutoff
1855			None	None	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Galvanic, Impressed Current
Diesel		2/16/2015	Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2	Automatic Tank Gauging 0.2, ELLD Line Tightness Testing	
15,000		11/14/2005	Gilbarco EMC Basic , Gilbarco		

Location: EUREKA MIDDLE SCHOOL **Sys Fac ID:** 27-04550

335 6TH ST E Last Inspected On: 3/11/2014

EUREKA, MT 59917 LINCOLN Operating Permit Renewal Date: 5/22/2017

Contact: Warren Powell, (406) 297-5729

Owners/Operators: Eureka Public Schools LCHS, Owner (406)-265-2525 PO BOX 2000

EUREKA MT 59917-2000

Warren M Powell, UST Class A Operator Warren M Powell, UST Class B Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	. .	Secondary Option Catastrophic L.D. Type 3.0	Secondary Option	Spill Protected
Status				Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
5	18	8/1/1997	Fiberglass Reinforced Plastic	Copper	Flapper Valve (Auto Shutoff)
1540		12/12/2012	None	Secondary Containment Chase	Yes
Currently in Use			Continuous Interstitial Monitoring	U.S. Suction	Not Applicable
Heating Oil			Automatic Tank Gauging 0.2	Manual Interstitial Monitor	
12,000			TS-1000, Incon		
6	18	8/1/1997	Fiberglass Reinforced Plastic	Copper	Flapper Valve (Auto Shutoff)
1541			None	Secondary Containment Chase	Yes
Temporarily Out of Use			Not Required	U.S. Suction	Not Applicable
Heating Oil			Automatic Tank Gauging 0.2	Not Listed	
8,000			TS-1000, Incon		

Location: KSANKA MOTEL & MINI MART

Sys Fac ID: 27-05303

US HIGHWAY 93 & MT HIGHWAY 37

Last Inspected On: 9/2/2014

EUREKA, MT 59917 LINCOLN

Operating Permit Renewal Date: 9/25/2017

Contact: Andre Hofstee, (406) 297-3127

Owners/Operators: Ksanka Enterprises, Owner

(406)-297-3127 PO BOX 857

EUREKA MT 59917-0857

Andre Hofstee, UST Class A Operator

Andre Hofstee, UST Class B Operator

Tank ld	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
4	25	4/20/1990	Cathodically Protected Steel	Fiberglass Reinforced Plastic	Ball Float Valve
3308			None	None	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Galvanic
Gasoline		4/13/2011	Automatic Tank Gauging 0.2	MLLD Line Tightness Testing	
10,000		7/29/2014	TLS-250 , Veeder Root		
5	25	4/20/1990	Cathodically Protected Steel	Fiberglass Reinforced Plastic	Ball Float Valve
3309			None	None	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Galvanic
Gasoline		7/29/2014	Automatic Tank Gauging 0.2	MLLD Line Tightness Testing	
6,000		7/29/2014	TLS-250 , Veeder Root		

TOWN PUMP INC EUREKA **Sys Fac ID: 27-08699** Location:

US HIGHWAY 93

Last Inspected On: 9/24/2014 EUREKA, MT 59917 LINCOLN **Operating Permit Renewal Date:** 10/16/2017

Roger Hovis, (406) 296-2431 Contact:

Owners/Operators: Eureka Town Pump Inc, Owner PO BOX 6000 (406)-497-6700

BUTTE MT 59702-6000

Trent Biggers, UST Class A Operator Trent Biggers, UST Class B Global Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
4	24	11/1/1991	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Ball Float Valve
2517			None	None	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Not Applicable
Gasoline		3/25/2010	Stat. Inventory Reconcilitation, Approved Remote Monitoring	Stat. Inventory Reconcilitation, Approved Remote Monitoring	
10,000			TLS-350/Gilbarco EMC , Veeder Root		
5	24	11/1/1991	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Ball Float Valve
2518			None	None	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Not Applicable
Gasoline		3/25/2010	Stat. Inventory Reconcilitation, Approved Remote Monitoring	Stat. Inventory Reconcilitation, Approved Remote Monitoring	
10,000			TLS-350/Gilbarco EMC , Veeder Root		
6	24	11/1/1991	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Ball Float Valve
2519			None	None	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Not Applicable
Gasoline		3/25/2010	Stat. Inventory Reconcilitation, Approved Remote Monitoring	Stat. Inventory Reconcilitation, Approved Remote Monitoring	
10,000			TLS-350/Gilbarco EMC , Veeder Root		
7	24	11/1/1991	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Ball Float Valve
2520			None	None	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Not Applicable
Gasoline		3/25/2010	Stat. Inventory Reconcilitation, Approved Remote Monitoring	Stat. Inventory Reconcilitation, Approved Remote Monitoring	
10,000			TLS-350/Gilbarco EMC , Veeder Root		

Location: TOWN PUMP INC EUREKA

US HIGHWAY 93

EUREKA, MT 59917 LINCOLN

Contact: Roger Hovis, (406) 296-2431

Sys Fac ID: 27-08699

Last Inspected On: 9/24/2014

Operating Permit Renewal Date: 10/16/2017

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
8	24	11/1/1991	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Ball Float Valve
2521			None	None	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Not Applicable
Diesel		3/25/2010	Stat. Inventory Reconcilitation, Approved Remote Monitoring	Stat. Inventory Reconcilitation, Approved Remote Monitoring	
12,000			TLS-350/Gilbarco EMC , Veeder Root		
9	15	11/1/2000	Fiberglass Reinforced Plastic	Flexible Plastic	Ball Float Valve
4251			Double-Walled	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Not Applicable
Diesel		3/25/2010	Continuous Interstitial Monitor, Stat. Inventory Reconcilitation, Approved Remote Monitoring	Stat. Inventory Reconcilitation, Approved Remote Monitoring	
10,000			TLS-350/Gilbarco EMC , Veeder Root	Continuous Interstitial Monitor	
10	15	11/1/2000	Fiberglass Reinforced Plastic	Flexible Plastic	Ball Float Valve
4252			Double-Walled	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Not Applicable
Diesel		3/25/2010	Continuous Interstitial Monitor, Stat. Inventory Reconcilitation, Approved Remote Monitoring	Stat. Inventory Reconcilitation, Approved Remote Monitoring	
5,000			TLS-350/Gilbarco EMC , Veeder Root	Continuous Interstitial Monitor	
11	01	3/14/2014	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff)
5467		3/19/2014	Double-Walled	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Not Applicable
Gasoline			Continuous Interstitial Monitor, Stat. Inventory Reconcilitation, Approved Remote Monitoring	Stat. Inventory Reconcilitation, Approved Remote Monitoring	
8,000			TLS-350/Gilbarco EMC , Veeder Root	Continuous Interstitial Monitor, Not Listed	Yes

TOWN PUMP INC EUREKA **Sys Fac ID**: 27-08699 Location:

US HIGHWAY 93

EUREKA, MT 59917 LINCOLN **Operating Permit Renewal Date:** 10/16/2017

Last Inspected On: 9/24/2014

Roger Hovis, (406) 296-2431 Contact:

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
12	01	3/14/2014	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff)
5468		3/19/2014	Double-Walled	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Not Applicable
Gasoline			Continuous Interstitial Monitor, Stat. Inventory Reconcilitation, Approved Remote Monitoring	Stat. Inventory Reconcilitation, Approved Remote Monitoring	
20,000			TLS-350/Gilbarco EMC , Veeder Root	Continuous Interstitial Monitor, Not Listed	Yes
13	01	3/14/2014	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff)
5469		3/19/2014	Double-Walled	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Not Applicable
Diesel			Continuous Interstitial Monitor, Stat. Inventory Reconcilitation, Approved Remote Monitoring	Stat. Inventory Reconcilitation, Approved Remote Monitoring	
8,000			TLS-350/Gilbarco EMC , Veeder Root	Continuous Interstitial Monitor, Not Listed	Yes

Location: RANCH HAND INC Sys Fac ID: 27-12713

1000 US HIGHWAY 93 N Last Inspected On: 1/26/2016

EUREKA, MT 59917 LINCOLN Operating Permit Renewal Date: 3/19/2019

Contact: Dustin Stoken, (406) 297-2342

(406)-296-2342 PO BOX 749 EUREKA MT 59917-0749

Pat Stoken, Owner (406)-296-2342 PO BOX 749

EUREKA MT 59917-0749

Dorothy Bickel, UST Class A Operator Destin Stoken, UST Class A Operator Dorothy Bickel, UST Class B Operator Destin Stoken, UST Class B Operator

Owners/Operators: Michael Stoken, Owner

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
8	17	5/1/1998	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Ball Float Valve
2960			None	None	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Not Applicable
Diesel			Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2	MLLD Line Tightness Testing	
20,000		1/13/2016	Gilbarco EMC Basic , Gilbarco		
9	17	5/1/1998	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Ball Float Valve
2961			None	None	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Not Applicable
Diesel			Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2	MLLD Line Tightness Testing	
15,000		1/13/2016	Gilbarco EMC Basic , Gilbarco		
10	17	5/1/1998	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Ball Float Valve
2962			None	None	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Not Applicable
Gasoline			Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2	MLLD Line Tightness Testing	
15,000		1/13/2016	Gilbarco EMC Basic , Gilbarco		

Location: RANCH HAND INC Sys Fac ID: 27-12713

1000 US HIGHWAY 93 N Last Inspected On: 1/26/2016

EUREKA, MT 59917 LINCOLN Operating Permit Renewal Date: 3/19/2019

Contact: Dustin Stoken, (406) 297-2342

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
11	17	5/1/1998	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Ball Float Valve
2963			None	None	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Not Applicable
Gasoline			Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2	MLLD Line Tightness Testing	
10,000		1/13/2016	Gilbarco EMC Basic , Gilbarco		
12	17	5/1/1998	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Ball Float Valve
2964			None	None	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Not Applicable
Gasoline			Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2	MLLD Line Tightness Testing	
10,000		1/13/2016	Gilbarco EMC Basic , Gilbarco		
13	17	5/1/1998	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Ball Float Valve
2965			None	None	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Not Applicable
Diesel			Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2	MLLD Line Tightness Testing	
2,000		1/13/2016	Gilbarco EMC Basic , Gilbarco		

Location: CRYSTAL LAKES RESORT INC Sys Fac ID: 27-03824

CRYSTAL LAKES RD Last Inspected On: 1/8/2013

FORTINE, MT 59918 LINCOLN Operating Permit Renewal Date: 4/2/2016

Contact: Robert LeBlanc, (406) 752-7662

Owners/Operators: James E Smith, Owner (406)-882-4432 PO BOX 255

FORTINE MT 59918-0255

James E Smith, UST Class A Operator James E Smith, UST Class B Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
1	29	6/1/1986	Cathodically Protected Steel	Steel	Flapper Valve (Auto Shutoff)
3892			None	None	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Impressed Current
Jet Fuel		10/4/2012	Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2	MLLD Line Tightness Testing	
10,000		10/4/2012			
2	29	6/1/1986	Cathodically Protected Steel	Steel	Flapper Valve (Auto Shutoff)
3893			None	None	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Impressed Current
Aviation Gas		10/4/2012	Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2	MLLD Line Tightness Testing	
10,000		10/4/2012			

FORTINE MERCANTILE US 93 Sys Fac ID: 27-13725 Location:

12000 US HIGHWAY 93 S Last Inspected On: 2/17/2015

FORTINE, MT 59918 **Operating Permit Renewal Date:** 3/26/2018 LINCOLN

Betty Stinger, (406) 882-4446

(406)-882-4446 PO BOX 215 TREGO MT 59934-0215

Debbie Peterson, UST Class A Operator Debbie Peterson, UST Class B Operator

Contact:

Owners/Operators: Betty Stinger, Owner

Tank ld	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
1	19	4/1/1996	Cathodically Protected Steel	Fiberglass Reinforced Plastic	Ball Float Valve
4705			None	None	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Galvanic
Gasoline		2/16/2015	Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2	MLLD Line Tightness Testing	
10,000		2/16/2015	Gilbarco EMC Basic , Gilbarco		
2	19	4/1/1996	Cathodically Protected Steel	Fiberglass Reinforced Plastic	Ball Float Valve
4706			None	None	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Galvanic
Gasoline		2/16/2015	Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2	MLLD Line Tightness Testing	
8,000		2/16/2015	Gilbarco EMC Basic , Gilbarco		
3	19	4/1/1996	Cathodically Protected Steel	Fiberglass Reinforced Plastic	Ball Float Valve
4707			None	None	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Galvanic
Diesel		2/16/2015	Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2	MLLD Line Tightness Testing	
4,000		2/16/2015	Gilbarco EMC Basic , Gilbarco		

Location: SAVE RITE WEST Sys Fac ID: 27-01239

31978 US HIGHWAY 2 Last Inspected On: 9/12/2013

LIBBY, MT 59923 LINCOLN Operating Permit Renewal Date: 10/17/2016

Contact: Rob Uithof, (406) 293-4119

(406)-293-4119 31978 US HIGHWAY 2 LIBBY MT 59923-3026

Lloyd Holcomb, UST Class A Operator Jesse Knapp, UST Class A Operator Lloyd Holcomb, UST Class B Operator Jesse Knapp, UST Class B Operator

Owners/Operators: Golden State Oil, Owner

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
3	21	3/1/1994	Fiberglass Reinforced Plastic	Flexible Plastic	Ball Float Valve
2158		9/16/2013	None	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	Pressurized	Not Applicable
Gasoline		5/18/2007	Automatic Tank Gauging 0.2	Continuous Interstitial Monitor	
10,000					
4	21	3/1/1994	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Ball Float Valve
2159		9/16/2013	None	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	Pressurized	Not Applicable
Gasoline		5/20/2010	Automatic Tank Gauging 0.2	Continuous Interstitial Monitor	
5,000					
5	21	3/1/1994	Fiberglass Reinforced Plastic	Flexible Plastic	Ball Float Valve
2160		9/16/2013	None	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	Pressurized	Not Applicable
Diesel		5/20/2010	Automatic Tank Gauging 0.2	Continuous Interstitial Monitor	
5,000					
12	18	6/1/1997	Cathodically Protected Steel	Flexible Plastic	Ball Float Valve
2161		9/16/2013	None	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	Pressurized	Galvanic
Gasoline		5/20/2010	Automatic Tank Gauging 0.2	Continuous Interstitial Monitor	
12,000		9/12/2013			

Location: SAVE RITE WEST

31978 US HIGHWAY 2

LIBBY, MT 59923 LINCOLN

Contact: Rob Uithof, (406) 293-4119

Sys Fac ID: 27-01239

Last Inspected On: 9/12/2013

Operating Permit Renewal Date: 10/17/2016

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
13	18	6/1/1997	Cathodically Protected Steel	Flexible Plastic	Ball Float Valve
2162		9/16/2013	None	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	Pressurized	Galvanic
Gasoline		5/20/2010	Automatic Tank Gauging 0.2	Continuous Interstitial Monitor	
3,000		9/12/2013			
14	18	6/1/1997	Cathodically Protected Steel	Flexible Plastic	Ball Float Valve
2163		9/16/2013	None	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	Pressurized	Galvanic
Diesel		5/20/2010	Automatic Tank Gauging 0.2	Continuous Interstitial Monitor	
12,000		9/12/2013			
15	18	6/1/1997	Cathodically Protected Steel	Flexible Plastic	Ball Float Valve
2164		9/16/2013	None	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	Pressurized	Galvanic
Diesel		5/20/2010	Automatic Tank Gauging 0.2	Continuous Interstitial Monitor	
6,000		9/12/2013			
16	18	6/1/1997	Cathodically Protected Steel	Flexible Plastic	Ball Float Valve
2165		9/16/2013	None	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	Pressurized	Galvanic
Diesel		5/20/2010	Automatic Tank Gauging 0.2	Continuous Interstitial Monitor	
4,000		9/12/2013			
17	18	6/1/1997	Cathodically Protected Steel	Flexible Plastic	Ball Float Valve
2166		9/16/2013	None	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	Pressurized	Galvanic
Diesel		5/20/2010	Automatic Tank Gauging 0.2	Continuous Interstitial Monitor	
3,000		9/12/2013			

Location: SAVE RITE SOUTH Sys Fac ID: 27-01240

33934 US HIGHWAY 2 Last Inspected On: 9/12/2013

LIBBY, MT 59923 LINCOLN Operating Permit Renewal Date: 10/17/2016

Contact: Robert Uithof, (406) 293-4119

(406)-293-4119 31978 US HIGHWAY 2 LIBBY MT 59923-3026

Lloyd Holcomb, UST Class A Operator Jesse Knapp, UST Class A Operator Lloyd Holcomb, UST Class B Operator Jesse Knapp, UST Class B Operator

Owners/Operators: Golden State Oil, Owner

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
1	26	5/1/1989	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Ball Float Valve
2168		9/12/2013	Double-Walled	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	Pressurized	Not Applicable
Gasoline		5/18/2007	Automatic Tank Gauging 0.2, Continuous Interstitial Monitor	Continuous Interstitial Monitor	
6,000		11/18/2010			
2	26	5/1/1989	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Ball Float Valve
2169		9/12/2013	Double-Walled	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	Pressurized	Not Applicable
Gasoline		5/18/2007	Automatic Tank Gauging 0.2, Continuous Interstitial Monitor	Continuous Interstitial Monitor	
4,000		11/18/2010			
6	26	5/1/1989	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Ball Float Valve
2167		9/12/2013	Double-Walled	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	Pressurized	Not Applicable
Gasoline		5/18/2007	Automatic Tank Gauging 0.2, Continuous Interstitial Monitor	Continuous Interstitial Monitor	
10,000		11/18/2010			
7	20	6/3/1995	Cathodically Protected Steel	Flexible Plastic	Ball Float Valve
2170		9/12/2013	None	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	Pressurized	Galvanic
Diesel		9/12/2013	Automatic Tank Gauging 0.2	Continuous Interstitial Monitor	
8,000		7/18/2007			

Location: SAVE RITE SOUTH

33934 US HIGHWAY 2

LIBBY, MT 59923 LINCOLN

Robert Uithof, (406) 293-4119 Contact:

Sys Fac ID: 27-01240

Last Inspected On: 9/12/2013 **Operating Permit Renewal Date:** 10/17/2016

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
3	20	6/3/1995	Cathodically Protected Steel	Flexible Plastic	Ball Float Valve
2171		9/12/2013	Double-Walled	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	Pressurized	Galvanic
Diesel		9/14/2013	Automatic Tank Gauging 0.2	Continuous Interstitial Monitor	
12,000		7/18/2007			
)	20	6/3/1995	Cathodically Protected Steel	Flexible Plastic	Ball Float Valve
2172		9/12/2013	Double-Walled	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	Pressurized	Galvanic
Gasoline		9/14/2013	Automatic Tank Gauging 0.2	Continuous Interstitial Monitor	
1,000		7/18/2007			
10	20	6/23/1995	Cathodically Protected Steel	Flexible Plastic	Ball Float Valve
173		9/12/2013	Double-Walled	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	Pressurized	Galvanic
Diesel		9/14/2013	Automatic Tank Gauging 0.2	Continuous Interstitial Monitor	
10,000		7/18/2007			
l1	20	6/23/1995	Cathodically Protected Steel	Flexible Plastic	Ball Float Valve
2174		9/12/2013	Double-Walled	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	Pressurized	Galvanic
Diesel		9/14/2013	Automatic Tank Gauging 0.2	Continuous Interstitial Monitor	
10,000		7/18/2007			
2	20	6/23/1995	Cathodically Protected Steel	Flexible Plastic	Ball Float Valve
2175		9/12/2013	Double-Walled	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	Pressurized	Galvanic
Gasoline		9/14/2013	Automatic Tank Gauging 0.2	Continuous Interstitial Monitor	
1,000		7/18/2007			

Location: ST JOHNS LUTHERAN HOSPITAL **Sys Fac ID:** 27-01695

350 LOUISIANA AVE

LIBBY, MT 59923 LINCOLN Operating Permit Renewal Date: 9/25/2017

Contact: Tony Rebo, (406) 293-0785

Owners/Operators: Cabinet Peaks Medical Center, Owner (406)-283-7000 209 HEALTH PARK DRIVE

LIBBY MT 59923

Tony Rebo, Operator (406)-283-7339 209 HEALTH PARK DRIVE

LIBBY MT 59923-2130

Tony Rebo, UST Class A Operator Tony Rebo, UST Class B Operator

Tank ld	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness ATG Type	Secondary Pipe Detection	Energy Act	
3	17	7/1/1998	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	High Level Alarm
1952		7/29/2014	Double-Walled	Double-Walled	Yes
Currently in Use			Auto Dialer	U.S. Suction	Not Applicable
Heating Oil			Continuous Interstitial Monitor	Continuous Interstitial Monitor	
4,000			TLS-300 , Veeder Root		

SEWER PLANT Location: **Sys Fac ID: 27-03164**

750 CITY SERVICE RD Last Inspected On: 11/19/2014

LIBBY, MT 59923 LINCOLN **Operating Permit Renewal Date:** 3/12/2018

Dan Burns, (406) 293-2775 Owners/Operators: City Of Libby, Owner PO BOX 1428

(406)-293-2775 LIBBY MT 59923-1428

Lucas Backen, UST Class A Operator Mike Voorhies, UST Class A Operator Mike Voorhies, UST Class B Operator Lucas Backen, UST Class B Global Operator

Contact:

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
5	29	12/1/1986	Fiberglass Reinforced Plastic	Steel	Flapper Valve (Auto Shutoff)
4089			None	none	Yes
Currently in Use		12/1/1996	Not Required	U.S. Suction	Not Applicable, Galvanic
Diesel		11/9/2011	Manual Tank Gauging	MLLD Line Tightness Testing	
550		11/9/2011			

Location: ASA WOOD SCHOOL Sys Fac ID: 27-05434

700 IDAHO AVE Last Inspected On: 1/12/2015

LIBBY, MT 59923 LINCOLN Operating Permit Renewal Date: 3/4/2018

Contact: Kirby Maki, (406) 293-2791

(406)-293-2791 724 LOUISIANA AVE LIBBY MT 59923-2106

Louie Mysse, UST Class A Operator Louie Mysse, UST Class B Global Operator

Owners/Operators: School Dist 4 Libby, Owner

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
1	22	10/1/1993	Cathodically Protected Steel	Flexible Plastic	Flapper Valve (Auto Shutoff)
1528			Double-Walled	Double-Walled	Yes
Currently in Use			Auto Dialer	U.S. Suction	Galvanic
Heating Oil		5/28/2015	Automatic Tank Gauging 0.2, Continuous Interstitial Monitor	MLLD Line Tightness Testing	
10,000		7/16/2015	EECO 1000, EMCO Electronics	Continuous Interstitial Monitor	

Location: MCGRADE SCHOOL UST Sys Fac ID: 27-05435

933 FARM TO MARKET RD STE C Last Inspected On: 1/12/2015

LIBBY, MT 59923 LINCOLN Operating Permit Renewal Date: 3/4/2018

Contact: Kirby Maki, (406) 293-8811

(406)-293-2791 724 LOUISIANA AVE LIBBY MT 59923-2106

Louie Mysse, UST Class A Operator Louie Mysse, UST Class B Global Operator

Owners/Operators: School Dist 4 Libby, Owner

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Га g Numbe r	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery Energy Act
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	
1	20	8/1/1995	Cathodically Protected Steel	Steel	High Level Alarm
1529			Double-Walled	Double-Walled	Yes
Currently in Use			Auto Dialer	U.S. Suction	Galvanic
Heating Oil		1/9/2015	Automatic Tank Gauging 0.1, Continuous Interstitial Monitor	MLLD Line Tightness Testing	
4,000		7/16/2015	EECO 1500, EMCO Electronics	Continuous Interstitial Monitor	

Location: PLUMMER ELEMENTARY SCHOOL Sys Fac ID: 27-05436

263 INDIAN HEAD RD Last Inspected On: 1/12/2015

LIBBY, MT 59923 LINCOLN Operating Permit Renewal Date: 2/19/2018

Contact: Kirby Maki, (406) 293-8811

(406)-293-2791 724 LOUISIANA AVE LIBBY MT 59923-2106

Louie Mysse, UST Class A Operator Louie Mysse, UST Class B Global Operator

Owners/Operators: School Dist 4 Libby, Owner

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
2	19	8/1/1996	Cathodically Protected Steel	Steel	Flapper Valve (Auto Shutoff)
1530			Double-Walled	Double-Walled	Yes
Currently in Use			Auto Dialer	U.S. Suction	Galvanic
Heating Oil		1/9/2015	Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2, Continuous Interstitial Monitor	Continuous Interstitial Monitor, Not Listed	
4,000			Gilbarco EMC Basic , Gilbarco		

Location: LIBBY HIGH SCHOOL DIST 4 Sys Fac ID: 27-05437

150 EDUCATION WAY Last Inspected On: 1/12/2015

LIBBY, MT 59923 LINCOLN Operating Permit Renewal Date: 3/4/2018

Contact: Kirby Maki, (406) 293-8811

(406)-293-2791 724 LOUISIANA AVE LIBBY MT 59923-2106

Louie Mysse, UST Class A Operator Louie Mysse, UST Class B Global Operator

Owners/Operators: School Dist 4 Libby, Owner

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
2	26	2/5/1990	Unknown	Copper	
1531	Yes		None	Double-Walled	Yes
Currently in Use			Auto Dialer	Pressurized	Not Applicable
Heating Oil		11/4/2011	Deferred	Continuous Interstitial Monitor	
2,000			Gilbarco EMC Basic , Gilbarco		
3	26	2/5/1990	Unknown	Copper	
1532	Yes		None	Double-Walled	Yes
Currently in Use			Auto Dialer	Pressurized	Not Applicable
Heating Oil		11/4/2011	Deferred	Continuous Interstitial Monitor	
2,000			Gilbarco EMC Basic , Gilbarco		
4	21	7/1/1994	Cathodically Protected Steel	Flexible Plastic	Flapper Valve (Auto Shutoff)
1533			Double-Walled	Double-Walled	Yes
Currently in Use			Auto Dialer	Pressurized	Galvanic
Heating Oil		1/9/2015	Continuous Interstitial Monitor	Continuous Interstitial Monitor	
10,000		5/28/2015	Gilbarco EMC Basic , Gilbarco		

Location: HAPPY'S ROADHOUSE INN Sys Fac ID: 27-05998

72576 US HWY 2 Last Inspected On: 1/21/2014

LIBBY, MT 59923 LINCOLN Operating Permit Renewal Date: 3/18/2017

Contact: Gerald Mick, (406) 293-4079

Owners/Operators: Carry L Mick, Owner/Operator (406)-293-4079 57 SMITH DRIVE

LIBBY MT 59923

Gerald L Mick, Owner/Operator (406)-293-4079 57 SMITH DRIVE LIBBY MT 59923

Carry Mick, UST Class A Operator Gerald Mick, UST Class A Operator Deb Steinke, UST Class A Operator Gerald Mick, UST Class B Operator

Deb Steinke, UST Class B Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
1	31	3/23/1984	Bare Steel	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff)
1282			Impressed Current	None	Yes
Currently in Use			Not Required	Safe Suction	Impressed Current
Diesel		1/16/2014	Automatic Tank Gauging 0.2	Deferred	
8,000			TS-1000, Incon		
2	31	3/23/1984	Bare Steel	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff)
1283			Impressed Current	None	Yes
Currently in Use			Not Required	Safe Suction	Impressed Current
Gasoline		1/16/2014	Automatic Tank Gauging 0.2	Deferred	
8,000			TS-1000, Incon		

Location: ST JOSEPH PARISH Sys Fac ID: 27-07289

719 UTAH AVE Last Inspected On: 9/7/2015

LIBBY, MT 59923 LINCOLN Operating Permit Renewal Date: 12/11/2018

Contact: (406) 293-4322

(406)-293-4322 PO BOX 1729 HELENA MT 59624-1729

HELENA MI 59624-172

Lauri A Youso, UST Class A Operator Lauri Youso, UST Class B Operator

Owners/Operators: Diocese of Helena, Owner

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
3	22	11/30/1993	Fiberglass Reinforced Plastic	Copper	Flapper Valve (Auto Shutoff)
833			Double-Walled	Secondary Containment Chase	Yes
Currently in Use			Not Required	U.S. Suction	Not Applicable
Heating Oil			Continuous Interstitial Monitor	Continuous Interstitial Monitor, Not Listed	
1,000			LDE Series , Pneumercator		

Location: LIBBY CENTRAL OFFICE 9080 B01 Sys Fac ID: 27-07386

114 E 4TH ST

LIBBY, MT 59923 LINCOLN Operating Permit Renewal Date: 7/31/2017

Contact: Ed Winkler, (406) 293-5848

Owners/Operators: Citizens Communications Company, Owner (916)-686-3499 ATTN BRIAN MCGUINNESS

(916)-686-3499 ATTN BRIAN MCGUINNESS 9260 E STOCKTON BLVD ELK GROVE CA 95624-1456 Last Inspected On: 7/9/2014

Alan Kelly, UST Class A Operator

Brian McGuinness, UST Class A Operator

Alan Kelly, UST Class B Operator

Brian McGuinness, UST Class B Global Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness ATG Type	ATG Type	Secondary Pipe Detection	Energy Act
1	24	8/1/1991	Fiberglass Reinforced Plastic	Steel	High Level Alarm
4307		7/9/2014	Double-Walled	Double-Walled	Yes
Currently in Use			Auto Dialer	Gravity Feed	Not Applicable
Diesel			Automatic Tank Gauging 0.2, Continuous Interstitial Monitor	Continuous Interstitial Monitor	
600			TLS-350/Gilbarco EMC , Veeder Root		

Location: HARLOWS SCHOOL BUS SERVICE INC LIBBY

Sys Fac ID: 27-07523

30772 US HIGHWAY 2

LIBBY, MT 59923 LINCOLN Operating Permit Renewal Date: 12/17/2017

Contact: Dan Zachreson, (406) 293-8845

Owners/Operators: Harlows School Bus Service Inc, Owner (406)-293-8845 30772 US HIGHWAY 2

LIBBY MT 59923-3130

Last Inspected On: 7/29/2014

Wesley Tangen, UST Class A Operator Hugh Taylor, UST Class A Operator Wesley Tangen, UST Class B Operator Hugh Taylor, UST Class B Operator

Tank ld	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
3	23	2/1/1993	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff)
3101			None	None	Yes
Currently in Use			Not Required	Safe Suction	Not Applicable
Diesel			Automatic Tank Gauging 0.2	Deferred	
2,000			TLS-300 , Veeder Root		
4	23	2/1/1993	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff)
3102			None	None	Yes
Currently in Use			Not Required	Safe Suction	Not Applicable
Diesel			Automatic Tank Gauging 0.2	Deferred	
2,000			TLS-300, Veeder Root		

Location: AITKENS QUIK STOP INC Sys Fac ID: 27-08831

120 W 9TH ST Last Inspected On: 1/8/2016

LIBBY, MT 59923 LINCOLN Operating Permit Renewal Date: 3/2/2019

Contact: Steve Bryant, (406) 293-6715

Owners/Operators: Aitkens Quik Stop Inc, Owner (406)-847-4080 ATTN JEFF AITKEN

1402 MT HIGHWAY 200 NOXON MT 59853-9750

Jeffrey Aitken, UST Class A Operator Jeffrey Aitken, UST Class B Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
3	41	11/21/1974	Cathodically Protected Steel	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff)
1274			Lined Interior/Impressed Current	None	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Impressed Current
Gasoline		2/19/2016	Automatic Tank Gauging 0.2	MLLD Line Tightness Testing	
8,000		1/6/2016	TLS-300 , Veeder Root		
4	41	11/21/1974	Cathodically Protected Steel	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff)
4881			Lined Interior/Impressed Current	None	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Impressed Current
Gasoline		2/19/2016	Automatic Tank Gauging 0.2	MLLD Line Tightness Testing	
10,000		1/6/2016	TLS-300 , Veeder Root		
5	41	11/21/1974	Cathodically Protected Steel	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff)
1276			Lined Interior/Impressed Current	None	Yes
Temporarily Out of U	se		Mechanical Line Leak Detector	Pressurized	Impressed Current
Gasoline		2/19/2016	Automatic Tank Gauging 0.2	MLLD Line Tightness Testing	
10,000		5/9/2012	TLS-300, Veeder Root		

MOORE OIL INC KARDGUARD **Sys Fac ID:** 27-10130 Location:

E 1ST ST & MONTANA AVE Last Inspected On: 9/13/2013

Operating Permit Renewal Date: 12/21/2016 LIBBY, MT 59923 LINCOLN

Larry Kelly, (406) 293-5947 Owners/Operators: Moore Oil Inc, Owner

(406)-827-4314 2718 TRADEWINDS WAY THOMPSON FALLS MT 59873-9706

Larry Kelly, UST Class A Operator Larry Kelly, UST Class B Global Operator

Contact:

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
1	31	12/19/1984	Bare Steel	Flexible Plastic	
1700	Yes	12/20/2012	None	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	Pressurized	Not Applicable
Diesel			Deferred	Continuous Interstitial Monitor	
20,000					
2	31	12/19/1984	Bare Steel	Flexible Plastic	
1701	Yes	12/20/2012	None	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	Pressurized	Not Applicable
Gasoline			Deferred	Continuous Interstitial Monitor	
20,000					
4	41	7/1/1974	Bare Steel	Flexible Plastic	
1702	Yes	12/20/2012	None	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	Pressurized	Not Applicable
Diesel			Deferred	Continuous Interstitial Monitor	
12,000					

MOORE OIL INC KEYLOCK **Sys Fac ID:** 27-10131 Location:

1328 US HIGHWAY 2 S Last Inspected On: 9/13/2013

LIBBY, MT 59923 Operating Permit Renewal Date: 11/12/2016 LINCOLN

Bary Moore, (406) 827-3498 Contact:

(406)-827-4314 2718 TRADEWINDS WAY

THOMPSON FALLS MT 59873-9706

Larry Kelly, UST Class A Operator Larry Kelly, UST Class B Global Operator

Owners/Operators: Moore Oil Inc, Owner

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recover
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
4	18	10/17/1997	Unknown	Flexible Plastic	
1703	Yes	12/20/2013	None	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	Pressurized	Not Applicable
Gasoline			Deferred	Continuous Interstitial Monitor	
12,000					
5	18	11/17/1997	Unknown	Flexible Plastic	
1704	Yes	12/20/2013	None	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	Pressurized	Not Applicable
Diesel			Deferred	Continuous Interstitial Monitor	
12,000					
6	18	10/17/1997	Unknown	Flexible Plastic	
1705	Yes	12/20/2013	None	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	Pressurized	Not Applicable
Gasoline			Deferred	Continuous Interstitial Monitor	
17,000					
7	18	10/17/1997	Unknown	Flexible Plastic	
1706	Yes	12/20/2013	None	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	Pressurized	Not Applicable
Diesel			Deferred	Continuous Interstitial Monitor	
12,000					

Location: MACS PLACE Sys Fac ID: 27-10660

1427 MT HIGHWAY 37 Last Inspected On: 5/15/2013

LIBBY, MT 59923 LINCOLN Operating Permit Renewal Date: 10/11/2016

Contact: Bill Avants, (406) 293-7799

Owners/Operators: Northside Enterprises LLC, Owner (406)-293-7799 1423 MT HIGHWAY 37

LIBBY MT 59923-9309

William Avants, Operator (406)-293-7799 1423 MT HIGHWAY 37

LIBBY MT 59923-9309

William Avants, UST Class A Operator William Avants, UST Class B Operator

Tank ld	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
1	40	3/23/1975	Cathodically Protected Steel	Steel	Flapper Valve (Auto Shutoff)
1272			Lined Interior/Impressed Current	None	Yes
Currently in Use			Not Required	Safe Suction	Impressed Current
Gasoline		11/12/2013	Automatic Tank Gauging 0.2	Deferred	
4,000		12/30/2005			
2	40	3/23/1975	Cathodically Protected Steel	Steel	Flapper Valve (Auto Shutoff)
1273			Lined Interior/Impressed Current	None	Yes
Currently in Use			Not Required	Safe Suction	Impressed Current
Gasoline		11/12/2013	Automatic Tank Gauging 0.2	Deferred	
12,000		12/30/2005			

Location: AITKENS QUIK STOP LIBBY

Owners/Operators: Aitkens Quik Stop Inc, Owner

Sys Fac ID: 27-10863

3490 US HIGHWAY 2 S

Last Inspected On: 11/19/2014

LIBBY, MT 59923 LINCOLN

Operating Permit Renewal Date: 3/31/2018

Contact: Jeff Aitken, (406) 293-9411

(406)-847-4080 ATTN JEFF AITKEN

1402 MT HIGHWAY 200 NOXON MT 59853-9750

Jeffrey Aitken, UST Class A Operator Jeffrey Aitken, UST Class B Operator

Tank ld	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
4	24	4/29/1991	Cathodically Protected Steel	Fiberglass Reinforced Plastic	Ball Float Valve
676			None	None	Yes
Currently in Use		10/2/2001	Mechanical Line Leak Detector	Pressurized	Galvanic
Diesel		11/18/2014	Tank Tightness Testing, Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2	MLLD Line Tightness Testing	
17,000		11/17/2014			
5	24	4/29/1991	Cathodically Protected Steel	Fiberglass Reinforced Plastic	Ball Float Valve
677			None	None	Yes
Currently in Use		10/2/2001	Mechanical Line Leak Detector	Pressurized	Galvanic
Diesel		11/18/2014	Tank Tightness Testing, Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2	MLLD Line Tightness Testing	
17,000		11/17/2014			
3	24	4/29/1991	Cathodically Protected Steel	Fiberglass Reinforced Plastic	Ball Float Valve
678			None	None	Yes
Currently in Use		10/2/2001	Mechanical Line Leak Detector	Pressurized	Galvanic
Gasoline		11/18/2014	Tank Tightness Testing, Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2	MLLD Line Tightness Testing	
10,000		11/17/2014			
7	24	4/29/1991	Cathodically Protected Steel	Fiberglass Reinforced Plastic	Ball Float Valve
679			None	None	Yes
Currently in Use		10/2/2001	Mechanical Line Leak Detector	Pressurized	Galvanic
Gasoline		11/18/2014	Tank Tightness Testing, Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2	MLLD Line Tightness Testing	
10,000		11/17/2014			

Report Generation Date: 3/1/2016

Location: AITKENS QUIK STOP LIBBY Sys Fac ID: 27-10863

3490 US HIGHWAY 2 S Last Inspected On: 11/19/2014

LIBBY, MT 59923 LINCOLN Operating Permit Renewal Date: 3/31/2018

Contact: Jeff Aitken, (406) 293-9411

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
3	24	4/29/1991	Cathodically Protected Steel	Fiberglass Reinforced Plastic	Ball Float Valve
80			None	None	Yes
Currently in Use		10/2/2001	Mechanical Line Leak Detector	Pressurized	Galvanic
Gasoline		11/18/2014	Tank Tightness Testing, Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2	MLLD Line Tightness Testing	
3,000		11/17/2014			

Location: **TOWN PUMP INC LIBBY 2 Sys Fac ID:** 56-14121

(406)-497-6700

US HIGHWAY 2 & E POPLAR ST Last Inspected On: 11/27/2015

LIBBY, MT 59923 LINCOLN Operating Permit Renewal Date: 3/5/2019

(406) 293-2222 Owners/Operators: Columbia Falls Holdings LLC, Owner PO BOX 6000

BUTTE MT 59702-6000

Charles A Armstrong, UST Class A Operator

Trent Biggers, UST Class A Operator Don Edmisten, UST Class A Operator

Contact:

Charles A Armstrong, UST Class B Global Operator

Trent Biggers, UST Class B Global Operator Don Edmisten, UST Class B Global Operator

Tank ld	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
1	11	6/9/2004	Fiberglass Reinforced Plastic	Flexible Plastic	Ball Float Valve
4922			Double-Walled	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Not Applicable
Gasoline			Continuous Interstitial Monitor, Stat. Inventory Reconcilitation, Approved Remote Monitoring	Stat. Inventory Reconcilitation, Approved Remote Monitoring	
15,000			TLS-350/Gilbarco EMC , Veeder Root	Continuous Interstitial Monitor	
2	11	6/9/2004	Fiberglass Reinforced Plastic	Flexible Plastic	Ball Float Valve
4923			Double-Walled	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Not Applicable
Gasoline			Continuous Interstitial Monitor, Stat. Inventory Reconcilitation, Approved Remote Monitoring	Stat. Inventory Reconcilitation, Approved Remote Monitoring	
10,000			TLS-350/Gilbarco EMC , Veeder Root	Continuous Interstitial Monitor	
3	11	6/9/2004	Fiberglass Reinforced Plastic	Flexible Plastic	Ball Float Valve
4924			Double-Walled	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Not Applicable
Gasoline			Continuous Interstitial Monitor, Stat. Inventory Reconcilitation, Approved Remote Monitoring	Stat. Inventory Reconcilitation, Approved Remote Monitoring	
5,000			TLS-350/Gilbarco EMC , Veeder Root	Continuous Interstitial Monitor	

Location: TOWN PUMP INC LIBBY 2

US HIGHWAY 2 & E POPLAR ST

LIBBY, MT 59923 LINCOLN

Contact: (406) 293-2222

Sys Fac ID: 56-14121

Last Inspected On: 11/27/2015

Operating Permit Renewal Date: 3/5/2019

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
4	11	6/9/2004	Fiberglass Reinforced Plastic	Flexible Plastic	Ball Float Valve
4925			Double-Walled	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Not Applicable
Diesel			Continuous Interstitial Monitor, Stat. Inventory Reconcilitation, Approved Remote Monitoring	Stat. Inventory Reconcilitation, Approved Remote Monitoring	
15,000			TLS-350/Gilbarco EMC , Veeder Root	Continuous Interstitial Monitor	
5	11	6/9/2004	Fiberglass Reinforced Plastic	Flexible Plastic	Ball Float Valve
4927			Double-Walled	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Not Applicable
Diesel			Continuous Interstitial Monitor, Stat. Inventory Reconcilitation, Approved Remote Monitoring	Stat. Inventory Reconcilitation, Approved Remote Monitoring	
10,000			TLS-350/Gilbarco EMC , Veeder Root	Continuous Interstitial Monitor	
6	11	6/9/2004	Fiberglass Reinforced Plastic	Flexible Plastic	Ball Float Valve
4928			Double-Walled	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Not Applicable
Diesel			Continuous Interstitial Monitor, Stat. Inventory Reconcilitation, Approved Remote Monitoring	Stat. Inventory Reconcilitation, Approved Remote Monitoring	
5,000			TLS-350/Gilbarco EMC , Veeder Root	Continuous Interstitial Monitor	

Location: CABINET PEAKS MEDICAL CENTER Sys Fac ID: 60-15252

209 HEALTH PARK DR Last Inspected On: 12/5/2014

LIBBY, MT 59923 LINCOLN Operating Permit Renewal Date: 12/19/2017

Contact: Tony Rebo, (406) 293-0785

Owners/Operators: Cabinet Peaks Medical Center, Owner (406)-283-7000 209 HEALTH PARK DRIVE

LIBBY MT 59923

Tony Rebo, UST Class A Operator Tony Rebo, UST Class B Operator

Tank ld	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
1	02	11/29/2013	Bare Steel	Flexible Plastic	High Level Alarm
5414	Yes	11/29/2014	Double-Walled	Double-Walled	Yes
Currently in Use			Auto Dialer	U.S. Suction	
Diesel			Continuous Interstitial Monitor, Deferred	Continuous Interstitial Monitor	
8,000			TLS-350/Gilbarco EMC , Veeder Root	Not Listed	

Location: TROY HIGH SCHOOL MISSOULA AVE **Sys Fac ID:** 27-00763

204 MISSOULA AVE Last Inspected On: 1/6/2016

TROY, MT 59935 LINCOLN Operating Permit Renewal Date: 3/2/2019

Contact: Dan Wendt, (406) 295-4606

(406)-295-4606 PO BOX 867 TROY MT 59935-0867

John L Daniel, UST Class A Operator Keith Haggerty, UST Class A Operator John L Daniel, UST Class B Global Operator Keith Haggerty, UST Class B Global Operator

Owners/Operators: School Dist 1 Troy, Owner

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
1	28	8/1/1987	Cathodically Protected Steel	Copper	Flapper Valve (Auto Shutoff)
2147			Excavation Liner	PVC	Yes
Currently in Use			Not Required	U.S. Suction	Galvanic
Heating Oil		1/6/2016	Manual Interstitial Monitor	Manual Interstitial Monitor	
10,000					
3	28	8/1/1987	Cathodically Protected Steel	Copper	Flapper Valve (Auto Shutoff)
2148			Double-Walled	PVC	Yes
Currently in Use			Not Required	U.S. Suction	Galvanic
Heating Oil		10/17/2012	Manual Interstitial Monitor	Manual Interstitial Monitor	
10,000					

Location: TROY ELEMENTARY SCHOOL Sys Fac ID: 27-00764

318 KALISPELL AVE Last Inspected On: 1/6/2016

TROY, MT 59935 LINCOLN Operating Permit Renewal Date: 3/2/2019

Contact: Dan Wendt, (406) 295-4606

Owners/Operators: School Dist 1 Troy, Owner (406)-295-4606 PO BOX 867

TROY MT 59935-0867

John L Daniel, UST Class A Operator Keith Haggerty, UST Class A Operator John L Daniel, UST Class B Global Operator Keith Haggerty, UST Class B Global Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
1	28	8/1/1987	Cathodically Protected Steel	Copper	Flapper Valve (Auto Shutoff)
2149			Excavation Liner	PVC	Yes
Currently in Use			Not Required	U.S. Suction	Galvanic
Heating Oil		1/6/2016	Manual Interstitial Monitor	Manual Interstitial Monitor	
10.000					

Location: CENEX/TROY MINI MART Sys Fac ID: 27-03253

217 E MISSOULA AVE Last Inspected On: 6/18/2013

TROY, MT 59935 LINCOLN Operating Permit Renewal Date: 9/11/2016

Contact: Joseph Lapham, (208) 263-7606

Owners/Operators: Joseph Lapham, Owner/Operator (208)-263-7606 1229 W ODEN BAY RD SANDPOINT ID 83864

Valerie Brown, UST Class A Operator Mike DuPerault, UST Class A Operator Kayla Eberly, UST Class A Operator Joseph Lapham, UST Class A Operator Paula Paasch, UST Class A Operator

Tank Id
Tag Number

Paula Paa	ascn, UST Class A Ope	rator		
Mark Roe	sler-Begalke, UST Clas	s A Operator		
Keith Wag	gner, UST Class A Ope	rator		
Nancy Wa	agner, UST Class A Op	erator		
Joseph La	apham, UST Class B O	perator		
•	ner, UST Class B Ope			
•	agner, UST Class B Op			
Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
	Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
	Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
	Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
22	4/12/1993	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Ball Float Valve
		None	None	Yes
		Mechanical Line Leak Detector	Pressurized	Not Applicable
		Automatic Tank Gauging 0.2	MLLD Line Tightness Testing	
	3/7/2013			

Status		inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP wet Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
1	22	4/12/1993	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Ball Float Valve
3132			None	None	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Not Applicable
Gasoline			Automatic Tank Gauging 0.2	MLLD Line Tightness Testing	
5,000		3/7/2013			
8	22	4/12/1993	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Ball Float Valve
3129			None	None	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Not Applicable
Gasoline			Automatic Tank Gauging 0.2	MLLD Line Tightness Testing	
8,000		3/7/2013			
9	22	4/12/1993	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Ball Float Valve
3130			None	None	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Not Applicable
Gasoline			Automatic Tank Gauging 0.2	MLLD Line Tightness Testing	
4,000		3/7/2013			

Location: CENEX/TROY MINI MART Sys Fac ID: 27-03253

217 E MISSOULA AVE Last Inspected On: 6/18/2013

TROY, MT 59935 LINCOLN Operating Permit Renewal Date: 9/11/2016

Contact: Joseph Lapham, (208) 263-7606

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
10	22	4/12/1993	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Ball Float Valve
3131			None	None	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Not Applicable
Diesel			Automatic Tank Gauging 0.2	MLLD Line Tightness Testing	
5,000		3/7/2013			

LINCOLN COUNTY SHOP TROY **Sys Fac ID: 27-06716** Location:

1210 E MISSOULA AVE

TROY, MT 59935 LINCOLN Operating Permit Renewal Date: 7/2/2016

Robert Downey, (406) 295-4420 Contact:

Owners/Operators: Lincoln County Road Dept, Owner

512 CALIFORNIA AVE (406)-295-4420 LIBBY MT 59923-1942 Last Inspected On: 2/26/2013

Dave Kyriss, UST Class A Operator Dave Kyriss, UST Class B Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
3	25	5/1/1990	Cathodically Protected Steel	Steel	Flapper Valve (Auto Shutoff)
1538			Double-Walled	none	Yes
Currently in Use			Not Required	Safe Suction	Galvanic
Diesel		2/26/2013	Continuous Interstitial Monitor	Deferred	
2,000					
4	25	5/1/1990	Cathodically Protected Steel	Steel	Flapper Valve (Auto Shutoff)
1539			Double-Walled	none	Yes
Currently in Use			Not Required	Safe Suction	Galvanic
Gasoline		2/26/2013	Continuous Interstitial Monitor	Deferred	
2,000					

Location: TROY CENTRAL OFFICE 9140 B01 Sys Fac ID: 27-08082

KOOTENAI AVE & 2ND ST

Last Inspected On: 6/18/2013

TROY, MT 59935 LINCOLN Operating Permit Renewal Date: 6/1/2016

Contact: Ed Winkler, (406) 293-5848

Owners/Operators: Citizens Communications Company, Owner (916)-686-3499 ATTN BRIAN MCGUINNESS 9260 E STOCKTON BLVD

9260 E STOCKTON BLVD ELK GROVE CA 95624-1456

John Jones, UST Class A Operator Brian McGuinness, UST Class A Operator Alan Kelly, UST Class B Operator

John Jones, UST Class B Global Operator Brian McGuinness, UST Class B Global Operator

Tank ld	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
1	24	8/1/1991	Unknown	Steel	
3272	Yes		None	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	Safe Suction	Not Applicable
Diesel			Deferred	Continuous Interstitial Monitor	
500					

Location: TOWN PUMP INC TROY

112 E MISSOULA AVE

TROY, MT 59935 LINCOLN

Contact: Roger Hovis, (406) 295-4921

Owners/Operators: Troy Town Pump Inc, Owner

Sys Fac ID: 27-08722

Last Inspected On: 12/14/2015

Operating Permit Renewal Date: 4/1/2019

(406)-497-6700 600 S MAIN ST

BUTTE MT 59701-2534

Charles A Armstrong, UST Class A Operator

Trent Biggers, UST Class A Operator Don Edmisten, UST Class A Operator

Charles A Armstrong, UST Class B Global Operator

Trent Biggers, UST Class B Global Operator Don Edmisten, UST Class B Global Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
1	35	4/14/1980	Cathodically Protected Steel	Fiberglass Reinforced Plastic	Ball Float Valve
2524			None	None	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Impressed Current
Gasoline		9/24/2014	Stat. Inventory Reconcilitation, Approved Remote Monitoring	Stat. Inventory Reconcilitation, Approved Remote Monitoring	
12,000			TLS-350/Gilbarco EMC , Veeder Root		
2	43	4/14/1972	Cathodically Protected Steel	Fiberglass Reinforced Plastic	Ball Float Valve
2523			Lined Interior/Impressed Current	None	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Impressed Current
Diesel		9/24/2014	Stat. Inventory Reconcilitation, Approved Remote Monitoring	Stat. Inventory Reconcilitation, Approved Remote Monitoring	
6,000			TLS-350/Gilbarco EMC , Veeder Root		
3	43	4/14/1972	Cathodically Protected Steel	Fiberglass Reinforced Plastic	Ball Float Valve
2522			Lined Interior/Impressed Current	None	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Impressed Current
Gasoline		9/24/2014	Stat. Inventory Reconcilitation, Approved Remote Monitoring	Stat. Inventory Reconcilitation, Approved Remote Monitoring	
12,000			TLS-350/Gilbarco EMC , Veeder Root		